USDA-FOREST SERVICE GP 0 940-	117		
Index File No. <u>C 21</u>	(Ref. FSM 71	SEARCH) Tract or 51.4) Survey No	Cor. No. <u>C 2]</u>
T <u>3 N</u> R. <u>37 E</u>	R.D. <u>Pendleton</u>	County <u>Umatilla</u>	
Merid. Willamette	N.F. <u>Umatilla</u>	State <u>Oregon</u>	
CORNER DIAGRAM	DESCRIBE CORNER MONUMEN	T FOUND	<del></del>
T3NR37E 1/4	NONE		
N S 2 S 1		• •	2
RPE2808 1976	A fir 36" diam. b with letter S vis	ears N 17° E., 17.82 ft.(2 ible inside of 6" overgrow for fence corner, fence re	27 lks) dist. wth.
PHOTO IDENTIFICATION DATA	P.		ŕ
Photo No	A fir snag 30" di	am. bears N 50° W., 3.96 1	ft.(6 lks) dist.
Filed At.	with visible axe	marks under 3" overgrowth.	3
Object Ident	DESCRIBE CORNER LOCATION F	RELATIVE TO NEAR-BY FEATURES, ALS	O HOW TO REACH CORNER
ident. By	Westerly from wes	t edge of Tollgate 3.5 mil w fence- Thence southerly	les to road south
PLANE COORDINATE POSITION DATA	miles to creek cr	ossing and road forks- The	hce on right fork
State Zone	0.6 miles to east-west fence.		
x	Corner is west al	ong fence 600 feet.	
Υ		ag on east gate post marke	ed 1/h corner is
Estab. By	west 600 feet.		4
- Janesiand Janla	Title Division RPE 28	Headquarters Dat 08 7/27/	7190-52 (3/68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a  $2\frac{1}{2}$ " brass cap on a 2" iron pipe 31" long 4" above the ground with a 6' steel fence post 3' south with sign 54-4 attached.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A larch 10" diam. bears N 08° W., 43.5 ft. dist. marked 1/4 S 2 BT with a sign 54-3 attached 6" below a band of red paint and with a brass washer marked RPE 2808 nailed flush with BT blaze.

			.10
Work Done By. James D. Hanley Title	Engineer Date 7/27/76 State Reg	istration No ORPE 2808	
_	Filed At: Pendleton, Oragon	Date 8/ /76	. II
	REMARKS		

Clear cut to south and east.

12