USDA-FOREST SERVICE		
Index File No D_25	CORNER_RECORD (SEARCH) Tract or	Cor.
3N R. 37E	R.D. Walla Walla County Umatilla	No
Merid. Willamette	N.F. Umatilla State Oregon	
T3N R37E R38E S 1/16 S1 RPE 2808 1976	DESCRIBE CORNER MONUMENT FOUND Found $2\frac{1}{2}$ " brass cap on a $2\frac{1}{2}$ " galv. iron projecting 3" out of the ground. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND A 16" western larch bears S 50 W, 51.75 healed double blaze.	
PHOTO IDENTIFICATION DATA Photo No. Filed At. Dispect Ident. dent. By Signature	DESCRIBE CORNER LOCATION RELATIVE TO MAR-BY FEATURES, ALSO HO Corner is located about \$00' south of a	nood
LANE COORDINATE POSITION DATA	running southwesterly. There is a wood location poster on the road.	post with
tote Zone(
Willing Wells	Title Division Headquarters PLS Pendleton, OR 9/18/9	FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Maintained existing corner monument by remounding it with earth. Set steel fence post South of corner and attached sign 54-2 and 54-9.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Narked 1 new bearing tree:

A 15" western larch bears N $81\frac{1}{2}^{0}$ W, 77.6' scribed S1/16 S1 BT. New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Attached signs 54-3 and 54-9 and painted face of blaze and a 6" red band

Attached signs 54-3 and 54-9 and painted face of blaze and a 6" random all bearing trees.

	10
Work Done By. W. R. Wells Title PIS Date 9/13/9 State Registration No. 1106	
Certified Cor. Record Prepared ? Yes X No Filed At. Umatilla Co. Surveyor Off . Date /2/3/	
REMARKS	

Index File No. D-25 T. 3N R. 37E M. Will Tract or Surv. No.

Cor.

	D (SEARCH) Tract-or-	o No <u>D_25</u>
_ R.D. <u>Pendleton</u>	County _ Umatilla	
_ N.F. <u>Umatilla</u>	State Oregon	
DESCRIBE CORNER MONUM	MENT FOUND	
		· .
DESCRIBE BEARING TREES	OR OTHER OFFICIAL ACCESSOR	IES FOUND
6		
_	•	
_ Westerly from w	est edge of Tollgate	3.6 miles to road south
crossing and ro Reforestation P to location tag	ad forks-Thehce on le roject P36 sign-Thehc which indicates 1/4 c	ft fork 0.9 miles to e northeasterly 0.2 mile
 8 Title Divisio		Date 7100 52 (2/50)
	R.D. Pendleton N.F. Umatilla DESCRIBE CORNER MONUN DESCRIBE BEARING TREES DESCRIBE CORNER LOCATION Westerly from westerly from westerly from westerly from westerly from the consing and rong Reforestation From to location tages. Corner is south	R.D. Pendleton County Umatilla N.F. Umatilla State Oregon DESCRIBE CORNER MONUMENT FOUND DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSOR Westerly from west edge of Tollgate between metal snow fences—Thence sou crossing and road forks—Thence on le Reforestation Project P36 sign—Thence to location tag which indicates 1/4 c Corner is south 490 feet.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Index File No.

D 25 J. 3 N

R. 37 E

wM.

Set a $2\frac{1}{2}$ " brass cap on a 2" iron pipe 31" long 6" above the ground at base of south side of a 14" fir with a 6' steel fence post 3' south with sign 54-4 attached. Placed sign 54-2 on north and west side of 14" fir.

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A larch 13" diam. bears S 50° W., 51.75 ft. dist. marked S 1/16 S 1 BT with sign 54.3 attached 6" below a band of red paint and with a brass washer marked RPE 2808 nailed flush with BT blaze.

<u> </u>							10
Work Done By James D. Hanley	Title.	Engineer	Date	7/28/76 Sto	ate Registration No. OR.PE	2808	
Certified Cor Record Prepared ? Yes	XX	Filed At:	Pendleton.	Oregon	Date 8/	/76	
		RI	MARKS				

Tract or Surv. No.

12

Cor.