USDA-FOREST SERVICE Index File No. X-21	CORNER_RECORD (SEARCH) Tract-or Cor. Cor. No No
T 3N R. 37E	R.D. WALLA WALLA CountyUMATILLA
Merid. <u>WILLAMETTE</u>	N.F. <u>UMATILLA</u> State <u>OREGON</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND Found no evidence of the original corner monument.
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND Found a 28 inch diameter Ponderosa Pine S10°E, 173 lks, alive and vigorous with blaze evident.
PHOTO IDENTIFICATION DATA Photo No Filed At	Found a 25 inch diameter Douglas Fir N45°W, 78 lks, alive and vigorous with blaze evident.
Object Ident, Ident. By Signature	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner falls on steep West face approximately
PLANE COORDINATE POSITION DATA State Zone X Y Estab. By	300 feet below top of ridge. No nearby roads.
han Ignaturaffe	Title Division Headquarters Date FS-7100-52 (3/68) 5 SUKUEYOR

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½"x30" aluminum pipe with aluminum cap marked as shown: Pipe is set 24 inches in the ground.

Raised mound of stone around monument, 4 ft. base to top of cap

T3N **R37E** S 35 S 36 1991 OPLS 644

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New BOs:

A 5/8"x30" iron pin with plastic cap marked BGA SURVEY MARKER bears East, 3.35 feet A 5/8"x30" iron pin with plastic cap marked BGA SURVEY MARKER bears South, 3.65 feet

Attached Bearing Tree and Land Survey Monument signs to the BTs Set a steel fencepost approximately 5 feet East with Land Survey Monument and Wilderness Boundary signs attached.

Work Done By. D.I. Griffith _ _{Title} _ Surveyor Date 8-01-91 State Registration No. OPLS 644 Certified Cor. Record Prepared ? Yes 🚟 No Filed At: Umatilla Co. Surveyor Off. 10-91 Date REMARKS

Witnesses: Jeff Petersen and Jim Bennett

Index File No. X1-21 T. 3N R. 37E WM. Tract or Surv. No. Cor. GPO: 1984 O - 439-095