CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Z - 17 DIAGRAM

History of original corner establishment:

The original corner was established by George S. Pershin, on November 3, 1878, under GLO contract No. 304, as follows:

Set a stone, 17" x 10" x 8", on a southwest rocky point for corner to sections 2, 3, 34 and 35, from which:

T3S R30E S34|S35 T4S R30E S2 PLS 1636 2004

A 20 " pine bears S34° W, 322 links.

Finding an error in his earlier survey, George S. Pershin, on September 6, 1879, under GLO contract No. 332, conducted a resurvey of the township line, and at this corner he:

Set a basalt stone, 17" x 10" x 6", on the south side of a ridge for the corner to sections 34, 35, 2 and 3, from which:

A 28" pine bears S45° E, 264 links (174.24 feet). A 28" pine bears S66° W, 264 links (174.24 feet).

This corner was made a corner of minimum control by the establishment of a closing corner for sections 2 and 3, a few days later in 1879, by George S. Pershin, under GLO contract No. 332.

Original corner evidence recovered:

Found the original corner stone solidly set in a mound of stones. The original corner stone is 19" x 10" x 9" and is plainly marked with two notches on the east edge, from which:

A down and badly burnt Ponderosa Pine, no marks remaining, with charred stump which bears S43° E, 177.1 feet.

An uprooted 40" Ponderosa Pine with partly healed and burnt blazes, chaining notch visible. Root hole bears S63° W, 177.5 feet

Monument and accessories established to perpetuate the original position of this corner:

In place of the corner stone, I set a 1" x 30" flared, galvanized iron pipe 22" into the ground. I bury the corner stone along the north side of the pipe and build a mound of stones around the pipe. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above, from which:

A 5/8" x 24" iron rod, set 23" into the ground 4 feet north of a small quartz outcrop, with a 3/4" brass washer, marked "PLS 1636 35", attached at ground level, bears N32° E, 103.0 feet.

A 11" Ponderosa Pine, scribed "T4S S2 BT", bears S55° 30' E, 179.0 feet.

A 18" Ponderosa Pine, scribed "R30E BT", bears S5° 30' W, 165.8 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 34", attached at ground level, bears N46° W, 109.5 feet.

I drive a steel fence post, with a BLM "K" tag attached, East, 0.5 feet of the corner.

RECEIVED BY

Umatilia County Spryeyor

Date 5-04

Rec'd By___

No. 04-92-R

Page 1 of 2

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Z - 17, T3S, R30E

The two new bearing trees are scribed on double blazes and have a 3/4" brass washer, marked "PLS 1636", nailed flush to the base of the lower blaze. Both new bearing trees have a "Bearing Object" sign nailed above the blazes and the new bearing tree to the southeast has a "Witness Post" sign nailed to the back side of the tree.

I hereby certify the above corner point was perpetuated as hereon described on April 30, 2004. Magnetic declination set in compass: 14° E. NAD '83 UTM Zone 11 position: 5013319N, 338076E (plus or minus two meters).

PROFESSIONAL LAND SURVEYOR OREGON SULY MAL 1878

Renews June 30, 2005

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

Page 2 of 2

RECEIVED BY

Umatilla County Surveyor

Date____5-0°

Rec'd By KK