History of original corner establishment:

The original corner was established by George S. Pershin on May 6, 1879, under contract number 319, as follows:

Set stone 16" x 12" x 10" on north slope for 1/4 section corner.

DIAGRAM T3S R31E 1/4 S3 S2 PLS 1636 1996

C-17

Description of corner evidence found:

Found a basalt stone, 14" x 12" x 11", solidly set in a large mound of stones and plainly marked "1/4" on the east face.

Description of monument and accessories I established to perpetuate the original location of this corner:

In the exact position occupied by the corner stone, I set a 1 1/2" x 30" iron pipe, 22" into the ground. A 2 1/2" brass cap attached is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 24" iron rod, set 22" into the ground with a 5/8" brass washer, marked "PLS 1636 S2", attached at ground level, bears S89°E,

A 5/8" x 24" iron rod, set 21" into the ground with a 1 1/2" aluminum cap attached, marked "PLS 1636 S2" with an arrow pointing toward the corner, bears S23°E, 46.3 feet.

A 5/8" x 24" iron rod, set 20" into the ground with a 5/8" brass washer, marked "PLS 1636 S3", attached at ground level, bears S72\*30'W, 55.9 feet.

A 5/8" x 36" iron rod, set 33" into the ground bears N24° 30'W, 36.0 feet.

I hereby certify the above corner point was perpetuated as hereon 20° E. described on November 11, 1996. Magnetic declination:

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON DENNIS L. GAYLORD Office of COUNTY SURVEYOR County of UMATILLA State of OREGON ....... I hereby certify that the within instrument was filed in thi for record on the...... day of...... , 19..... ..... by ......

Form R6-7100-57 (9/71)

RECRIVED BY Umatilla County Surveyor