CERTIFIED RECORD OF LAND CORNER MONUMENTATION

C - 9 DIAGRAM

History of original corner establishment:

The original corner was established by George S. Pershin on May 14, 1879, under GLO contract No. 319, as follows:

Set a basalt stone 24" x 14" x 9" on west face of hill for 1/4 section corner.

T3S R31E 1/4 S5¦S4 PLS 1636 1998

Corner evidence recovered:

The original corner stone is solildy set in a mound of stones. The stone is 26" x 14" x 8" and is plainly marked "1/4" on the east face.

Monument and accessories established to perpetuate the original location of this corner:

At the point occupied by the original corner stone, I set a 1" x 30" iron pipe, 26" into the ground. A 2 1/2" brass cap attached to the pipe is marked as shown in the diagram above. I bury the corner stone along the west side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 24" iron rod set 21" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level bears N50°30'E, 74.3 feet. A 5/8" x 24" iron rod set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level bears S29°E, 186.5 feet. A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level bears S37°30'W, 119.1 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level bears N44°W, 113.0 feet.

I hereby certify the above corner point was perpetuated as hereon described on April 1, 1998. Magnetic declination: 18°E.

PROFESSIONAL LAND SURVEYOR

> OREGON/ DENNIS L. GAYLORD 1636

Renews June 30, 1999

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on _______, 1998.

RECEIVED BY

Umatilla County Surveyor

Date____

Bac'd By_X/

No. 98-69-K