History of original corner establishment: Corner was originally established by George S. Pershin, U.S. Deputy Surveyor, under Contract No. 304, dated September 19, 1878. The original notes state that at the corner a 4" dia Fir was marked from which:

A 13" dia. Pine bears S56°E 28 LK dist. A 10" dia. Tamarack bears N50°W 7 lk dist.

No restoration appears in County Records.

L-25	_
DIAGRAM	
T3S	
R31E_R32E	
4/4S13	
1	

Description of corner evidence found:

A 14" dia, tamarack bears N50°W 4.62 ft dist (old BT) fallen over. Visible scribing "S BT".

Description of monument and accessories I established to perpetuate the original location of this corner:

Measuring record bearing and distance from the center of the root hole at the base of the downed tree, I re-established the corner where I set:

A 2/11/2" brass cap on 2 1/2" x 30" 1. pipe 20" in the ground with mound of stone from which:

A 12" dia. W. Fir bears N19°W 30.0 ft dist marked: 1/4 S13 BT. A 9" dia. W. Fir bears S8°W 43.4 ft dist marked: 1/4 S13 BT.

Blaze faces and 6" band around bearing trees are painted red. Trees tagged with 54-3 and 4 signs. New BTs have lower blaze, scribed BT, with brass washer stamped PLS 1106 nailed flush.

Set steel fence post, with 54-4 sign attached North of corner.

Used steel tape and magnetic compass 19 3/4° East declination. Measured to center of BTs.

Corner monumented on October 18, 1982. Cap marked: T3S Witnessed by: Leslie E. Wilson R31E R32E PROFESSIONAL 1/45 13 LAND SURVEYOR 1982 PLS 1106 Willing R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS Umatilla ..... I hereby certify that the within instrument was filed in this office By of December 1982 H Krumbeen by (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor \*\* OPO -- 790.276