USDA-FOREST SERVICE Index R-25 T 3S R. 31E	CORNER RECORD (SEARCH)  (Ref. FSM 7151.4)  R.D County	Tract or Sec 25 Cor. NE Cor Umatilla
Merid. <u>Willamette</u>	N.F. <u>Umatilla</u> State	Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
T3S R32E	None.	
S24 S25 R31E		
• • • • • • • • • • • • • • • • • • • •	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	
	None. Corner was re-established range line.	l by single proporation measure along
PHOTO IDENTIFICATION DATA Photo No. 616140 780-7 Filed At. Umatilia Nat. Forest Object Ident. Trees Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO	NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	Yellow Jacket Road South to road	d #5415, then East on road #5415 approx.
PLANE COORDINATE POSITION DATA State Zone X	3/4 mile to cattleguard and N-S of fence in timber to corner.	fence, then 250 ft North on West side
Y	Carlos Ca	
Willin R. Wells	Title Division Head PLS 1106	Quarters Date 7100-52 (3, 68) 5

## CORNER RECORD (PERPETUATION)

NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set 2 1/2" brass cap on 2 1/2" x 30" 1. pipe 24" in ground with mound of stone.

Set stee! fence post, with 54-2 and 4 signs attached, North of corner.

1982 PIS 1106 ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE A 10" dia Red Fir bears N66°W 73.7 ft dist marked: T3S R31E S24 BT.

A 8" dia Red Fir bears S19°W 28.3 ft dist marked: T3S R31E S25 BT. Blaze faces and 6" band around bearing trees are painted red. Tagged trees with 54-3 and 4 signs. New BTs have lower blaze, scribed BT, with brass washer stamped PLS 1106 nailed flush.

Cap marked:

R3S R32E

S24 S29

**R31E** 

W.R. Wells Surveyor PLS 1106 Work Done By.\_ Title Filed At: Umatilla County Surveyor Office Certified Cor. Record Prepared ? Yes X No. Date

REMARKS

Witnessed by: Leslie E. Wilson

Index File No. T. R. Tract or Surv. No. Cor. 35 R-25 31E W.M. NE Cor Sec 25