USDA-FOREST SERVICE	• •
Index	CORNER RECORD (SEARCH) Tract or Cor.
File No. V=15 T 3S R 31E	- Survey No. Sec 34 No. N 1/4
Merid. Willamette	R.D. Ukiah County Umatilla
CORNER DIAGRAM	N.F. Umatilla State Oregon
	DESCRIBE CORNER MONUMENT FOUND
T3S R31E	3" brass cap on 2 1/2" I. pipe in mound of stone.
1 1/4 S27	
$\overline{534}$	
Ň	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	A 29" dig P. Pine brs N 57°W 74 T St. History C CORPTA T 5
I	A 29" dia P.Pine brs N57°W 74.1 ft dist tagg S57°E74.1 ft dist (of BT
	visible scribe).
	A 13" dia P.Pine brs S16°W 174.0 ft dist tagg N15°E 262½ lk dist-recent
PHOTO IDENTIFICATION DATA	LL.
Photo No. 616140 380-4	blaze.
Filed At. Umatilla Nat. Fores	+
Object Ident. Trees	
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	1 Rodd "3420 to rodd "5412-100, then West approx 2.1 m:1
PLANE COORDINATE POSITION DATA	#5412-100, then 40 ft North to corner in Swiss Meadows, just North of
	timber line and fence.
State Zone	Timber fille drid fence.
×	
Υ	
Estab. By	r .
Agency	4
Signature	Title Division Headquarters Date 7100-52 (3,68)
Willie Ruells	PLS 1106 October 6, 1982 5
	0010001 0, 1702

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set steel fence post with 54-4 sign attached, West of corner.

Standard BLM. Cap marked:

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Blaze faces and 6" bands around bearing trees are painted red. Tagged trees with 54-3 and 4 signs, where needed.

Date 10/6/82 State Registration No. PLS 1106 Work Done By ._ W.R. Wells Surveyor Title Filed At: Umatilla County Surveyor Office Certified Cor. Record Prepared ? YesX No REMARKS

Witnessed by: Leslie E. Wilson

R.

31E

35

T3S

R31E

1978

Index File No.

Tract or Surv. No. Cor. Sec 34

W.M.

Index V-15 File No. V-15 T 3S R 31E Merid. Willamette	R.D. <u>Ukiah County Umatilla</u> N.F. <u>Umatilla</u> Stote <u>Oregon</u> Cor. <u>V=15</u> R.D. Umatilla
CORNER DIAGRAM_	DESCRIBE CORNER MONUMENT FOUND
Section Section	Material: Stone mound. Size: Mound 24-inch diameter. One foot above ground; good condition. No markings visible. Stone is approximately the same as G.L.O. descriptions is set in the ground.
6	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND An 18-inch p.pine bears N60°W, approximately 70 feet. It has old "Oregon State Board of Forestry" location poster. Some scribing visible (B.T.). A 20-inch, partially rotted pine stump bears S12°W, approximately
Photo No	70 feet. No scribing visible, but it fits the proper location.
Object Ident. Ident. By: Signature 7 PLANE COORDINATE POSITION DATA	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER to Corner is about 50 feet north of main road from Carney Butte to Bear Wallow G.S.
State Zone X Y Estab. By	
Signature	Title Division Headquarters Date 7100-52 gineering Technician S. O. November 1, 1974 REV. 65 5

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I set a loose post in the stone mound and tied red and white striped ribbon on it.

I placed blank B.T. tags on both the B.T. and the B.T. stump.

							 10
Work Done By		_ Title	·	Date	State Registration or Agency	n No.	
Certified Cor. Reco	rd Prepared ? Yes	No	Filed At:			Date	 <u> 31</u>
	· · · · · · · · · · · · · · · · · · ·		DE	MARKS			

Index File No. T.

M.

Tract or Surv. No.

Cor.