USDA-FOREST SERVICE Index File No. V-17 T 3S R. 31E Merid. Willamette	CORNER RECORD (SEARCH) Tract or Survey No. Sec 34 No. NE Corner Corner Corner Corner No. NE Corner County County County County County Corner C
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T3S R31E <u>\$27 \$26</u> <u>\$34 \$35</u>	3" brass cap on 2 1/2" I. pipe protruding 6" from ground with mound of stone.
Ņ	
PHOTO IDENTIFICATION DATA Photo No. 616140 380-4 Filed At Umatilla Nat. Forest Object Ident. Trees Ident. By	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND A 24"dia P.St.brs N32°W32.2 ft dist tagg S32°E32.2 ft dist (old BT rot.out) A 22"dia P.Pine brsS21°W21.7ft dist tagg N21°E32 lk dist (oldBT, heal.blaze A 11"dia R.Fir brs N46°E45.1 ft dist tagg N45°W682k dist-recent blaze. A 11"dia R.Fir brs S49°E19.9 ft dist tagg N47½°W30½k dist-recent blaze. A 17"dia R.Fir brs N41°W23.8 ft dist tagg S41° 35 lk dist-recent blaze. DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X Y Estab. By	Road #5420 to road 5412-100, then West on road 5412-100 approx. 1.4 miles to $E^{\frac{1}{4}}$ corner then North on first road past $E^{\frac{1}{4}}$ cor and following the road to a gate in the fence, then North along fence approx. 1,800 ft to corner in fence in timbered flat.
Signature	Title Division Headquarters Date 7100 50 40 100
Willia R. Well	PLS 1106 October 7, 1982

CORNER RECORD (PERPETUATION)

T3S

S27 | S26

\$34 | \$35 1978

R31E

Set steel fence post with 54-4 sign attached, South of corner.

Standard BLM.

Cap marked:

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Blaze faces and 6" bands around bearing trees are painted red. Tagged trees with 54-3 & 4 signs where needed.

Work Done By W.R. Wells Title	Surveyor	Date 10/7/82 State Registration N	• PLS 1106	
Certified Cor. Record Prepared ? Yes X No		0000	ite	
	0544040			

Witnessed by: Leslie E. Wilson

Index File No. T. R. M. Tract or Surv. No. Cor. 13
V-17 3S 31E W.M. Sec 34 NE Cor

	CORNER RECORD (SEARCH) Tract or Survey No. 5 - 1 No. V-17				
T 3S R. 31E	R.D. <u>Ukiah</u> County <u>Umatilla</u>				
Merid. Willamette	N.F. Umatilla State Oregon				
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND				
1	Material: Basalt stone. Size: 18" x 12" x 5"				
No. 34	Ten inches above ground; good condition. Has 5 notches on north edge. Sets in north-south fence line beside large stone mound. (Mound is 4 feet in diameter, and 2 feet deep.)				
34	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND A 30-Inch down fir bears N20°E, approximately 53 feet. No visible scribing. SE B.T. gone.				
PHOTO IDENTIFICATION DATA	An 18-inch p.pine bears S21 ^o W, approximately 21 feet. Closed				
Photo No.	blaze faces corner.				
Filed At.	A 36-inch pine stump, very rotten, bears N34 ⁰ W, approximately 32 feet. A broken off segment is clearly (cont. in block 12)3				
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER				
Ident. By Signature 7	Corner stone sets in north-south fence line. Follow fence north				
PLANE COORDINATE POSITION DATA	from 4 corner between Sections 34 and 35.				
State Zone X Y	See Carney Bette 7.5 minute quadrant map.				
Estab. By	<u> </u>				
Signature T. Hollamon En	Title Division Headquarters Date 7100-52 gineering Technician S. O. November 7, 1974 REV. 65 5				

CORNER	RECORD	(PERPETUATION)
--------	--------	----------------

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed blank B. T. tag on both the NW B. T. stump segment and the SW B. T.

Work Done By_______ Title______ Date_____ State Registration No.

Certified Cor. Record Prepared ? Yes No Filed At:

Date

REMARKS

(Block #3, cont.) scribed T35, R31E, S27, B.T.

- 12