USDA-FOREST SERVICE GPO 940	)+117
Index File NoX-25	CORNER RECORD (SEARCH) Tract or 5-72 Cor.
T <u>3S</u> R. <u>31E</u> Merid. Willamette	County Umatilia
CORNER DIAGRAM	Title Stute
Section	Material: Stone mound.  Monumented By BLM, 1978  No visible markings (show on ground). Mound is rock jack in fence.
36	An 18-inch p.pine bears S88°E, approximately 65 feet. Scribed \$\frac{1}{4}\$ S, B.T. Scribing has been chopped out. Tree has an "Attention" poster on east side and an orange ring painted around
PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident.	A 22-inch p.pine, N45 <sup>o</sup> W, approximately 32 feet. Scribed ¼ S, B.T. Scribing has been chopped out. Tree has an "Attention" poster on west side. (cont. in block #12.)
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	Approximate corner sets in a north-south fence about 200 feet
PLANE COORDINATE POSITION DATA	south of cattleguard on old logging road. (See Granite Meadows
State Zone	7.5 minute quadrant map.)
Estab. By	ing sa taon ang kalanggan ang Alanggan ang Kalanggan ang kalanggan ang kalanggan ang kalanggan ang kalanggan a Langgan kalanggan ang kalanggan ang Alanggan ang kalanggan ang kalanggan ang kalanggan ang kalanggan ang kalang
Signature T. Hollamon Eng	Title Division Headquarters Date 1974 7100-52 (3/68) S.O. November 25, 1974 7100-52 (3/68)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed a blank B.T. tag on each B.T. I also placed a location poster on a 10-inch p.pine about 20 feet south of cattleguard.

						10
Work Done By	Title _			Date	State Registration No. or Agency	
Certified Cor. Record Prepared ?	Yes No	Filed At:			Date	 - 11
	•		14040			

(cont. from block #3.)

It also has 2 old location poster on east side. There is an orange ring painted around the tree.

Index File No. T. R. M. Tract or Surv. No. Cor.

13