	Y-13
History of original corner establishment:	DIAGRAM
	T3S R31E
None.	S 1/16
	\$33 \ \$34
No record of corner establishment found in County Records.	
Description of corner evidence found:	
None.	
Description of monument and accessories I established to perpetuate the original location of this corner:	
Set 2 1/2" brass cap on 2 1/2" x 30" 1. pipe 24" in ground with mound of	earth from which:
A 12 1/2" dia Fir bears N63°W 42.2 ft dist marked: S 1/16 S33 BT. A 10" dia Pine bears S22°E 97.0 ft dist marked: S 1/16 S34 BT.	
Total Copy September 1999 (1995) (Copy Copy Copy Copy Copy Copy Copy Copy	
Blaze faces and 6" bands around bearing trees are painted red. Tagged trees. BTs have a lower blaze, scribed BT, with a brass washer stamped PLS 1100	
Set steel fence posts, with 54-9 sign on one and 54-2 signs on both, South	and East of corner.
Used steel tape and magnetic compass 19 3/4° East declination. Measured	to center of BTs.
Corner monumented on October 25, 1982. Cap marked:	1
With the District Property of the DC	Too nour
Witnessed by: Robert D. English PC D. L. Kaufman PLS	T3S R31E S 1/16
	S33 S34
REGISTERED	1982 PLS 1106
PROFESSIONAL LAND SURVEYOR	
Willie R. Wells	
OREGON	
JULY 22, 1977 WILLIAM R. WELLS	
1106	
Office of County Surveyor County of Umatilla	
State of Oregon I hereby certify that the within instrument was filed in the for report on the	is office
Daniel H. Krum bean Betty of Shatto	
(COUNTY OFFICIAL) (DEPUTY)	
Form R6-7100-57 (9/71)	RECLIVED BY
	Umatilla County Surveyor
	Date
	Rec'd By
	No. 82-138-B