


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Y-15

History of original corner establishment:

None.

No record of corner establishment in County Records.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2" brass cap on 2 1/2" x 30" l. pipe 24" in ground with mound of earth from which:

A 13" dia Pine bears N81 1/2° W 17.3 ft dist marked: CS 1/16 S34 BT.

A 10" dia Fir bears N5° E 44.0 ft dist marked: CS 1/16 S34 BT.

Blaze: faces and 6" bands around bearing trees are painted red. Tagged trees with 54- 3 & 9 signs. BTs have a lower blaze, scribed BT, with brass washer stamped PLS 1106 nailed flush.


Set steel fence posts with 54-9 sign on one and 54-2 signs on both, North and West of corner.

Used steel tape and magnetic compass 19 3/4° East declination. Measured to center of BTs.


Corner monumented on October 25, 1982.

Cap marked:

Witnessed by: Robert D. English PC
D. L. Kaufman PLS



William R. Wells



Office of... County Surveyor County of... Umatilla
Oregon
State of... I hereby certify that the within instrument was filed in this office
for record on the 15th day of December, 1982
Robert D. English by *Betty L. Shatt*
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor
Date _____
Rec'd by _____
No. 82-138-B