CERTIFIED RECORD OF LAND CORNER MONUMENTATION

C - 13 DIAGRAM

History of original corner establishment:

The original corner was established by George S. Pershin on May 22, 1882, under GLO contract No. 430, as follows:

Set basalt stone, 18" x 14" x 12", in a mound of stone on west slope, marked 1/4 on west face. Raised a mound of stones in lieu of pits.

T3S R32E 1/4 S4 S3 PLS 1636 1999

Corner evidence recovered:

Found the original corner stone loosely set in a mound of stones in an east-west barbed-wire fence. Corner stone is 18" x 12" x 10" and is plainly marked "1/4".

Monument and accessories established to perpetuate the original position of this corner:

At the position occupied by the original corner stone, I set a 1" \times 30" iron pipe 18" into the ground to bedrock. A 2 1/2" brass cap attached is marked as shown in the diagram above. I bury the corner stone along the southwest side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N4) E, 100.0 feet. A 5/8" x 36" iron rod set 30" into the ground in a small mound of stones, with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S25 E, 134.5 feet.

bears S25°E, 134.5 feet.
A 27" Ponderosa Pine, scribed "1/4 S4 BT" on double blazes with a 3/4" brass washer, marked "PLS 1636", nailed flush to the scribed "B", bears S31° 15"W, 240.0 feet. This tree has a "Bearing Object" sign nailed above the blazes.

A 5/8" x 36" iron rod set 30" into the ground in a small mound of stones, with a 3/4" brass washer, marked "PLS 1636 S4", attached at ground level, bears N28 30'W, 81.3 feet.

I hereby certify the above corner point was perpetuated as hereon described on August 27, 1999. Magnetic declination: 18 E

PROFESSIONAL LAND SURVEYOR

ORUGUN JULY 14, 1978 DENNIS L. GAYLORD 1636

Renews June 30, 2001

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on _______, 1999.

RECEIVED BY

Umatilla County Surveyor

Rao'd Dy KE

No 99-14/8-R