History of original corner establishment:

Corner originally established by George S. Pershin on May 17, 1882 under contract No. 430 as follows: Set a basalt stone 20" x 12" x 5" in a mound of stone in an open glade on level marked with 4 notches on the south and

1 notch on the east edges from which: A 32" Pine bears S 23°E, 133 links (87.78 feet) marked

T3S R32E S13 BT.

A 28" Pine bears N 77° W, 183 links (120.78 feet) marked T3S R32E S11 BT.

No other trees available.

T3S R32E S11 | S12 S14 | S13 LS 1636

1987

Description of corner evidence found:

By reference from the original bearing tree evidence, I find the corner point falls in a large mound of stones in a fence corner. Fences extend north and west from the corner. There are several stones in the mound of record size, but I am unable to identify a marked stone. From the corner point: A broken and decayed Ponderosa Pine stump, with the decayed remains of the tree lying alongside with scribe "B" visible, bears N77°W, 120.8 feet. A root hole, with the decayed Ponderosa Pine lying alongside with scribes "T3S R32E S" visible, bears S20°E, 87.8 feet.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position as determined by reference from the original bearing trees, I set a 2 1/2" x 30" aluminum pipe, with a 2 1/2" aluminum cap attached, 15" into the ground. The cap is marked as shown in the diagram. I build a mound of stones around and over the capped pipe, from which new bearing trees:

A 13" Ponderosa Pine bears ${\rm N68}^{\rm O}{\rm W}$, 47.9 feet scribed "T3S R32E S11 BT" on a single blaze.

A 17" Douglas Fir bears N11°E, 22.1 feet scribed "T3S R32E S12 BT" on a double blaze.

A 24" Ponderosa Pine bears $S36^{\circ}E$, 104.6 feet scribed "T3S R32E S13 BT" on a single blaze.

A 16" Ponderosa Pine bears S63°W, 92.6 feet scribed "T3S R32E S14 BT" on a single blaze.

Each new BT has a 3/4" brass washer, marked "PLS 1636", nailed flush to the blaze in the scribed "B", and a "bearing tree" and "Attention" sign nailed above the blaze.

I hereby certify this corner position was perpetuated as hereon described on June 9, 1987. De: 10° E. This declination is affected by the close proximity of fence wires, which are about 4" from my compass. Witness: Warren McCann

Form R6-7100-57 (9/71)

Umatilla County Surveyed

Red'd by

☆ GPO-798-276

REGISTERED PROFESSIONAL LAND SURVEYOR