USDA-FOREST SERVICE	
Index File No. N-7	CORNER RECORD (SEARCH) Tract or Sec 20 Cor. N 1/4
T3S R32E	R.D. Ukiah County Umatilla
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T3S R32E	3" brass cap on 2 1/2" I. pipe 15" out of ground with mound of stone.
$1/4 \frac{17}{20}$	
Ŋ	2
PHOTO IDENTIFICATION DATA Photo No. 616140 78.0-8 Filed At. Umatilla Nat. Forest Object Ident. Trees Ident. By  Signature 7	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  Yellow Jacket Road to road #5415, East to road #050. North approx. 13
PLANE COORDINATE POSITION DATA State Zone	miles to road going West across open ridge towards fence (N-S) then North along road to end of road then 300 ft North to corner on East side of drain-
X	age in clearing on Westerly face of slope.
Estab. By	
Willing R. Well	PLS 1106  Division Headquarters Date 7100-52 (3,68)  October 4, 1982

		•	
CORNER	RECORD	(PERPETUA	MOIT

Set steel fence post with 54-2 and 4 signs West of corner.

Cap is standard BLM.

T35 R32E

Cap marked:  $\frac{517}{520}$ 1977

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
Blaze faces and band around bearing trees are painted red. Tagged trees with 54-3 and 4 signs where needed.

Work Done By. W.R. Wells Title Surveyor Date 10/4/82 State Registration No. PLS 1106

Certified Cor. Record Prepared ? Yes X No Filed At: Umatilla County Surveyor Office Date 11

REMARKS

Witnessed by: Leslie E. Wilson

 Index File No.
 T.
 R.
 M.
 Tract or Surv. No.
 Cor.

 N−7
 3S
 32E
 W⋅M⋅
 Sec 20
 N 1/4