INDEX TO THE TOTAL PROPERTY OF THE TOTAL PRO	CORNER RECORD (SEARCH) Tract or Survey No. S 27 Cor. C 1/4
T 3S R. 32E	R.D. <u>Uklah</u> County <u>Umatilla</u>
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
C 1/4 . S27	None
Ņ	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
1	None
6	
PHOTO IDENTIFICATION DATA	1
Photo No.	
Filed At.	
Object ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	Road #54 to road #5412 then West to 1 #010 at the road at the road #5412
Signature 7	Road #54 to road #5412, then West to road #010, then North 3/4 miles
PLANE COORDINATE POSITION DATA	then South 100 feet to comer.
State Zone	In meadow west of old cabin.
x	
Υ	
Estab. By	
Agency 8	<u></u>
Willin Rrusell	PLS 1106 Division Headquarters Date Date October 13, 1982 October 13, 1982

. .

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2 1/2" brass cap on 2 1/2" x 30" I. pipe 22" in the ground and surrounded with T3S R32E mound of stone. Set steel fence posts, w/54-9 sign and 54-2 signs, North C 1/4 . S27 and East near corner.

Cap Marked: 1982

PLS 1106

A 14" P. Pine bears S17°E - 88.3 ft. dist. marked: T3S R32E C 1/4 S27 BT.
A 18" P. Pine bears S87°W - 32.3 ft. dist. marked: T3S R32E C 1/4 S27 BT.
Painted red 6" band around bearing trees and blaze faces. Tagged trees w/54-3 & 9 signs.
New BTS have lower blaze, scribed BT, with brass washer stamped PLS 1106 nailed flush.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By	W. R. Wells	Title_	Surveyor	Date 10/14/82State Registration	n No.	PLS 1106	
Certified Cor. R	ecord Prepared ? Yes	X No	Filed At: Umatilla	County Surveyor Office	Date		

Witnessed by: Leslie E. Wilson Larry Henshaw

Index_File_No. T. 3S R. 32E M. W.M. Tract or Surv. No. S27 Cor. C 1/4