CERTIFIED RECORD OF LAND CORNER MONUMENTATION

	U-18
History of original corner establishment:	DIAGRAM
None.	T3S R32E SW 1/16
	s26
	320
Description of corner evidence found:	
News	
None.	
Description of monument and accessories I established to perpeturoriginal location of this corner: Set 2 1/2" brass cap on 2 1/2" x 30" I, pipe 6" in the g	
A 19" dia. P. Pine bears N74°E 34.2 ft. dist. marked: A 15" dia. P. Pine bears S16°W 83.6 ft. dist. marked: A steel fence post North and West of corner with 54-2 s	SW 1/16 S26 BT.
Blaze faces and 6" band around bearing trees painted re	d. Trees tagged with 54-3 and 9 signs. Nev
BTs have lower blaze, scribed BT, with brass washer star Used steel tape and magnetic compass 19 3/4° East decl	
Corner monumented on October 14, 1982.	ap marked:
Witnessed by: Leslie E. Wilson	T3S R32E
Larry Henshaw	SW 1/16
	s26
PROFESSIONAL	1982 PLS 1106
LAND SURVEYOR	
Willia R. Weels	25
O R E G O N JULY 22, 1977	
WILLIAM R. WELLS	(4
Office of County Surveyor	Jmatilla
State of Oregon , I hereby certify that the within in for pacord on the 15 day of December , 1982	strument was filed in this office
Land Hrumbein by Betty	(DEPUTY)
Form R6-7100-57 (9/71)	RECEIVED BY 798.276
77,77	Umatilla County Surveyor
	Date
	No. 82-136-B
	10.02-136-13