CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner was originally established by George S. Pershin, U.S. Deputy Surveyor, under Contract No. 430, dated May 15, 1882. The original notes state that at the comer a granite stone 18" x 14" x 3" was set 12" in ground on East slope marked 1/4 on North face.

V-19 DIAGRAM T3S R32E 1/4 526 **S35**

No trees, raised mound of stone along-side in lieu of pits.

No restoration appears in County Records.

Description of corner evidence found:

Found 23" x 16" x 3" granite stone marked 1/4, lying on its side.

From location of stumps around comer stone it is evident it has not been disturbed, but has just fell over.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2 1/2" brass cap on 2 1/2" x 30" I. pipe 24" in the ground with mound of earth to cap. (Buried stone along-side monument) from which:

A RM bears \$482°E 30.73 ft. dist. marked T3\$ R32E \$35 RM. A RM bears N 102°E 26.80 ft. dist. marked T3S R32E S26 RM. Reference monuments were set because no live trees were within limits. Set steel fence posts, w/54-4 signs, on section line near comer. Used steel tape and magnetic compass 19 3/4° declination.

Reference monument example: Reference monuments are $2\frac{1}{2}$ " x 30" iron pipes with 2½" brass caps set 24" in ground and surrounded with a mound of earth.

T3S R32E **S26** RM 26.80 Ft. 1982 PLS 1106

Brass cap at comer marked:

T35 R32E 1/4 S26 **S35** 1982 PLS 1106

Comer set on September 29, 1982. Witnessed by: Leslie E. Wilson

REGISTERED PROFESSIONAL LAND SURVEYOR

Villia R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS

Office of County Surveyor County of.....

COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIV_D BY Umatilla County Suffer you

Date_