## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract No.410, George S. Pershin set a post, from which a 16" Fir bears North, 70 lks. and an 18" Pine bears S56°W, 14 lks.

Index-File No. Z-19 DIAGRAM T3S R33E T4S

Description of corner evidence found:

No corner monument found.

Bearing trees found: A 25" Fir bears N7°E, 46.6 ft., blaze healed.

A 24" W. Larch (called pine in original notes) bears S56°W, 9.8 ft. to center of tree, blaze healed, dead standing.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 6", stamped:

T3S R33E

An 11" Fir bears S68°E, 11.7 ft., scribed 1/4 S2 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

T4S **RLS 1848** 1984

Compass Declination: 19 1/2°E

Witness: G. Arrand .

Set a metal fence post 4 ft, north of corner.

From 2110-230, follow 2110-232 southeasterly to the end of the meadow. Corner is east across meadow and 150 ft. into the woods.

I hereby certify the above described corner monument and/or accessories was established as described on June 8, 1984.

REGISTERED PROFESSIONAL ND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

...... County of Umatilla COUNTY OFFICIALI hereby certify that the within instrument was filed in this office elly Cochran (DEPUTY)

Form R6-7100-57 (9/71)