

OREGON CORNER RESTORATION FORM

SECTION 28 TOWNSHIP 4 NORTH RANGE 27 EAST

V-13

COUNTY : UMATILLA DATE 12/02

CORNER DESIGNATION

SE CORNER

CONDITION REPORT ONLY

NOT FOUND

RENEWED

UNCOVERED

SURVEYED IN

REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED UNDER CONTRACT #209 IN 1874 BY WALDEN.


HARRIS SET A 2 1/2" BRASS CAP IN 1966 SURVEY FOR UMATILLA COUNTY.

EDWARDS SET A 5/8" IRON REBAR OVER HARRIS BRASS CAP IN 1993 SURVEY FOR LOGSDON.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE


A 5/8" IRON ROD.

MONUMENT DETAIL



NAD 83/91
OREGON STATE PLANE
INTERNATIONAL FEET

776664.3961
8473749.8374



MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A SCRIBE ON THE WESTERLY FACE AT THE TOP OF A IRON GUARD POST LIES N 52°14'25" E, 77.02 FEET.

A SCRIBE ON THE WESTERLY FACE AT THE TOP OF A IRON GUARD POST LIES N 89°38'22" E, 60.65 FEET.

AN IRRIGATION RISER LIES S 28°46'38" W, 80.60 FEET.

A 5/8" x 30" IRON ROD WITH A YELLOW PLASTIC CAP MKD "PLS LS 48509" LIES N 69°38'36" W, 47.40 FEET.

LOCATION AND COMMENTS

FROM INTERSECTION OF COUNTY LINE RD.
AND FRONTAGE RD. GO SOUTH 0.7 MILES
TO CORNER, CORNER FALLS ON EAST EDGE
OF COUNTY LINE RD. & WEST OF GRAVEL
PIT AREA.

COMPASS DEC.

FIRM/AGENCY
PRIMM LAND SURVEYING
P.O. BOX 1322
HERMISTON, OREGON 97838

PARTY CHIEF
KEITH P. PRIMM

NOTES

WITNESS
BRIT L. PRIMM

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Brit L. Primm
OREGON
JULY 13, 1999
BRIT L. PRIMM
48509

EXPIRATION DATE: 12/31/04

03-49-9