

OREGON CORNER RESTORATION FORM

SECTION 25 TOWNSHIP 4N RANGE 28

V-23

COUNTY: UMATILLA DATE 11/91

CORNER DESIGNATION

South 1/4 Corner

CONDITION REPORT ONLY
 NOT FOUND
 RENEWED
 UNRECORDED
 SURVEYED IN
 REFERENCED OUT

PREVIOUS RENEWALS/SURVEYS, ETC.

Originally surveyed in 1860 by Taft under Contract #93. He set post, made mound and deposited a pint of charcoal.

MONUMENTS & ACCESSORIES FOUND: Condition and Source
Nothing found.

MONUMENT DETAIL

SKETCH

T4N R28E
25
1/4
36
1991
LS 951

MONUMENT SET (PROCEDURES AND DESCRIPTION)

1 set 2 3/8" Brass Cap on 1" x 30" Iron pipe, stamped as above, 28" in ground. Drove steel fence post with Witness sign attached, 2 feet South. See my County Survey #1991-2.

NEW ACCESSORIES From which

A 1/2" x 27" Iron pipe with Alum. tag #951 Bears North 23.29 feet.
A 5/8" x 30" rebar with Alum. tag #951 Bears N 89° 43' 50" W 19.29 feet.
A 1/2" x 24" rebar with Alum. tag #951 Bears South 17.55 ft.
A square 1" tubing, with 951 stamped on West side, Bears S 89° 43' 50" E 18.28 feet.

LOCATION & COMMENTS

From Coe Street RR-crossing in Stanfield, go westerly along southerly side of tracks 2.0 miles. Corner lies South of tracks and 100 ± feet South of crest of hill.

COMPASS DEC.
FIRM EDWARDS SURVEYING
P.O. BOX 763, HERMISTON,
OREGON, 97838
PARTY CHIEF D. EDWARDS
NOTES
WITNESS S. BENEFIT

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RECEIVED BY

Umatilla County Surveyor

Date 4-92

Rec'd By KK

No. 92-45-C