

OREGON CORNER RESTORATION FORM


Section 2 Township 3N Range 28E
 County Umatilla Date: 06-14-02

Corner Designation: 3N28A21

_____x_____	Condition Report Only
	Not Found
	Re monumented
	Unrecorded
_____x_____	Surveyed In
	Referenced Out

Previous Renewals / Surveys, etc.
 Survey S-156-C set witness corners at this point.

Monument and Accessories Found: (condition and source)
 Found one brass capped witness corner as shown below.
 Northern witness corner not found.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.

Made GPS tie to TRI Station Stanfield East Base. Latitude 45°46'36.85883"N Longitude 119°16'09.68071"W NAD 83(1991) Coordinates are for southern witness corner.	Oregon State Plane Coord. - North Zone Northing 771743.73 Easting 8516088.48 Ortho Height 568.78 Ellipsoidal Height 499.00
--	--

Location and Comments Compass Declination Surveyors Seal

20°E

From the junction of Stanfield Meadows Road and Echo Meadows Road, go west 1.6 miles on Stanfield Meadows Road. Follow fence line south 0.3 mile and then east 0.25 mile. The witness corner is located on the south side of the irrigation ditch.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

RECEIVED BY: Firm / Agency

Date: 7-02
 Rec'd By: KK
 No. 02-185-9

Haddock Surveying
 P. O. Box 1574
 Pendleton, OR 97801
 (541) 276-2174

David L. Haddock

OREGON
 JULY 12, 1968
 DAVID L. HADDOCK
 852