OREGON CORNER RESTORATION **FORM**

SECTION 14,15 TOWNSHIP 4 NORTH RANGE 29 EAST

COUNTY : UMATILLA DATE MAY/20

CORNER DESIGNATION

CORNER

REPORT ONLY

X CONDITION RE
NOT FOUND
X RENEWED
UNCOVERED
SURVEYED IN
REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT IN A MOUND OF EARTH AND A CHARRED STAKE.

EDWARDS SET A 2 3/8" BC IN 2012. #101. H SET \mathbf{A} POST

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

A A A \mathbf{A} A 5/8" IRON A 5/8" IRON A 5/8" IRON 1 5/8" IRON F 2 3/8" BC 3/8" BC STAMPED " IRON ROD WITH A PLASTIC
" IRON ROD WITH A PLASTIC
" IRON ROD WITH A PLASTIC
" IRON ROD WITH A PLASTIC PLASTIC PLASTIC BELOW. CAP CAP "#951" LIES "#951" LIES "#951" LIES LIES SSSS 44°39'47" 37°50'04" 42°48'04" 43"11"39" $\tilde{\mathbb{L}} \times \times \tilde{\mathbb{L}}$ 18.53 19.52 22.85 17.83 FEET. FEET. FEET. FEET.

MONUMENT DETAIL

SKETCH

NAD 83/91 OREGON STATE INTERNATIONAL T4V S15 S14 S 2012 1/4 95/ PLANE

5/8" IRON ROD WITH PLASTIC O MKD "#951"

5/8" IRON ROD WITH PLASTIC (MKD "#951" CAP

5/8' IRON ROD WITH PLASTIC (MKD "#951"

CAP

CORNER

5/8" IRON ROD WITH PLASTIC (MKD "#951" CAP

790826.34 8542757.86

PROCEDURES AND DESCRIPTION)

MONUMENT SET

NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

FROM INTERSECTION OF LOOP RD. AND HIGHLAND EXTENSION GO WEST ON HIGHLAND EXTENSION 0.5 MILE THEN GO SOUTH 0.5 MILE ACROSS FIELD TO CORNER.

COMPASS DEC.

PRIMM LAND SURVEYING P.O. BOX 1322 HERMISTON, OREGON 97838 FIRM/AGENCY

۵. CHIEF PILCH

WITNESS KEITH P. PRIMM

> SURVEYOR'S SEAL

LAND REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 12, 200
KEITH P. PR 12, 2005 H P. PRIMM 48490

EXPIRATION DATE: 12/31/20

¥

400

DEC 20