CORNER RESTORATION FORM

Township 4N Range 28E, 29E Section 13,18,19,24 County UMATILLA
State OREGON Date 3/30/2023 Number N-1 Condition Report Only
Corner Designation: SECTION CORNER: 13, 18, 19, 24 Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER — Surveyed In
ORIGINALLY SURVEYED IN 1860 BY CAMPBELL UNDER X Referenced
CONTRACT #95, HE SET A STAKE IN MOUND OF EARTH
1954 HIGGINS SET 1/2" REINFORCING STEEL MONUMENT DETAIL
1973 KRUMBEIN SET BRASS CAP (LATER REJECTED) COUNTY
SURVEY NO. H-217-C X Found Set
1980 KRUMBEIN SET BRASS CAP 6" UNDER SURFACE OF ROAD
COUNTY SURVEY NO. S-156-C
2020 KRUMBEIN SET A 2 3/8" BRASS CAP IN MON. BOX
COUNTY SURVEY NO. 20-085-B
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: NORTHING: 787622.25 EASTING: 8521135.32
2020
Monument & Accessories Set/Found (Procedure and Description)
AT CORNER FOUND 2 3/8" BRASS CAP IN MON BOX, AS PER COUNTY SURVEY NO. 20-085-B
FOUND ALUMINUM TAG 951 ON SAWED OFF P.P. AND SET UMATILLA SURVEY MON. SIGN N 71°36' E 45.37',
AS PER CORNER FORM NO. N1-92-045-C
FOUND ALUMINUM TAG 951 ON SAWED OFF P.P. S 68°38' E 46.48', AS PER COUNTY FORM NO. N1-92-045-C
FOUND 2 3/8" BRASS CAP 6" BELOW ASPHALT N 33°44' E 22.97' (KRUMBEIN REJECTED 1973"), AS PER
COUNTY SURVEY NO. H-217-C
SET P.K. NAIL W/WASHER "PLS 61420" IN RXR TIE FENCE CORNER S 44°04' W 46.79'

