# OREGON CORNER RESTORATION FORM

SECTION 16,21 TOWNSHIP 4 NORTH RANGE 29 EAST

N - 11

COUNTY: UMATILLA

DATE 01/02

CORNER DESIGNATION

X CONDITION REPORT ONLY

\_\_NOT FOUND RENEWED

1/4 CORNER

\_\_ UNCOVERED \_\_SURVEYED IN

REFERENCED

#### PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101. HE SET A POST IN A MOUND OF EARTH AND A CHARRED STAKE.

IN 1995 EDWARDS SET A 1" x 30" IRON PIPE WITH A 2 3/8" BRASS CAP STAMPED AS BELOW, BY SINGLE PROPORTION.

### MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

A 2" x 48" ANGLE IRON WITH WITNESS SIGN LIES N 03'34'22" E, 1.25 FEET.
A 5/8" x 30" IRON ROD WITH A PLASTIC CAP MKD "#951" LIES S 89'09'40" W, 10.08 FEET.
A 1 1/4" x 33" IRON ROD LIES S 00'01'36" W, 10.07 FEET. A 1/2" x 24" IRON ROD WITH ALUM. CAP MKD #951 LIES N 88'47'18" E, 10.07 FEET.

SKETCH MONUMENT DETAIL 2" x 48" ANGLE IRON WITH WITNESS SIGN. 5/8" x 30" IRON ROD WITH YELLOW PLASTIC CAP. N 03\*34'22" E, 1.25" MKD "#951" N 88'47'18' E T4N R29E S 89\*09'40' W 10.07 10.08 1/4 CORNER 1/2" x 24" IRON ROD WITH ALUM. CAP. MKD "#951" .10.00 1995 15 951 N.T.S NAD 83/91 OREGON STATE PLANE INTERNATIONAL FEET 1 1/4" x 33" IRON ROD 787953.6159 8534880.5833

MONUMENT SET ( PROCEDURES AND DESCRIPTION )

NEW ACCESSORIES FROM WHICH

RECEIVED BY

Umatilla County Survey

-02

Date

Rec'd By.

SURVEYOR'S SEAL

REGISTERED

PROFESSIONAL LAND SURVEYOR

OREGON JULY 13, 1999 BRIT L. PRIMM 48509

EXPIRATITION DATE:12/31/02

## LOCATION AND COMMENTS

FROM INTERSECTION OF HIGHLAND EXTENSION WITH EDWARDS ROAD GO SOUTH ON EDWARDS ROAD 1 MILE THEN EAST ACROSS FIELD TO CORNER 1/2 MILE.

## COMPASS DEC.

FIRM/AGENCY PRIMM LAND SURVEYING P.O. BOX 1322 HERMISTON, OREGON 97838

PARTY CHIEF KEITH P. PRIMM

NOTES

WITNESS BRIT L. PRIMM