CORNER RESTORATION FORM

Township 4N Range 29E Section 14,15,22,23 County UMATILLA
State OREGON Date 3/30/2023 Number N-17 X Condition Report Only
Corner Designation: SECTION CORNER: 14, 15, 22, 23 —— Not Found
Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER ———————————————————————————————————
ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER
CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH MONUMENT DETAIL
1998 EDWARDS SET A 2 3/8" BRASS CAP COUNTY SURVEY NO. X Found Set
98-213-C
T4N R29E
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: 15 14 NORTHING: 788186.68
EASTING: 8542821.78
Monument & Accessories Set/Found (Procedure and Description)
AT CORNER FOUND A 2 3/8" BRASS CAP & UMATILLA MON. SIGN, COUNTY SURVEY NO. 98-213-C
FOUND A 5/8" I.R. W/PLASTIC CAP UNREADABLE S 89°51' W 24.61', CORNER FORM NO. N21-98-213-C
FOUND A 5/8" I.R. W/PLASTIC CAP UNREADABLE N 88°29' E 19.86', CORNER FORM NO. N21-01-213-G
FOUND A 5/8" I.R. 6" BELOW GRADE S 00°19'W 13.89', CORNER FORM NO. N21-01-213-G
FOUND A 5/8" I.R. 6" BELOW GRADE BENT SOUTH TIED SPINHOLE IN FIELD N 00°57' W 19.37', CORNER FORM
NO. N21-98-213-C
Sketch of Monument, Accessories and General Area REGISTERED PROFESSIONAL LAND SURVEYOR
FIELD

