## OREGON CORNER RESTORATION FORM

SECTION 14,23 TOWNSHIP 4 NORTH RANGE 29

COUNTY : UMATILLA DATE MAY/20

CORNER DESIGNATION

CORNER

Z <u>.</u>

REPORT ONLY


X CONDITION RE
NOT FOUND
X RENEWED
UNCOVERED
SURVEYED IN
X REFERENCED

PREVIOUS RENEWALS / SURVEYS, EIC.


ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101. IN A MOUND OF EARTH AND A CHARRED STAKE. IN 1998 EDWARDS SET A 2" ALUMINUM CAP STAMPED AS BELOW. Æ SET  $\triangleright$ POST

## MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

5/8" IRON ROD WITH A PLASTIC CAP MKD 5/8" IRON ROD WITH A PLASTIC CAP MKD 5/8" IRON ROD WITH A PLASTIC CAP MKD 2" ALUMINUM CAP STAMPED AS BELOW. "951" LIES "951" LIES "951" LIES S 46.02,16" S 89.55,39" S 82.55,49"  $\mathbb{M} \lesssim \mathbb{R}$ 22.35 17.86 29.62 FEET FEET FEET



MONUMENT DETAIL



MONUMENT PROCEDURES ₽ DESCRIPTION )

NEW ACCESSORIES FROM WHICH

A 5/8" × 30" IRON ROD WITH A YELLOW PLASTIC CAP MKD "PLS S 48490" LIES Z 21.21,42" Ĺ 56.85 FEET.

LOCATION AND COMMENTS

CENTERLINE OF LOOP RD. MILE NORTH OF FEEDVILLE RD.

> COMPASS DEC.

PRIMM LAND SURVEYING P.O. BOX 1322 HERMISTON, OREGON 97838 FIRM/AGENCY

PAUL PARTY ۵. CHEF PILCH

KEIT WITNESS 9 PRIMM

SURVEYOR'S SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR

HITA '48490' '2, 2005' 'H P. PRIMM OREGON Y 12, 20 I P. PF

EXPIRATION DATE: 12/31/20

DEC: