OREGON CORNER RESTORATION **FORM**

SECTION 13,14,23,24 TOWNSHIP 4 NORTH RANGE 29 EAST

COUNTY : UMATILLA DATE MAY/20

CORNER DESIGNATION

SECTION CORNER

> REPORT ONLY

N - 21

X CONDITION RE
NOT FOUND
X RENEWED
___UNCOVERED
__SURVEYED IN
__REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101. HE
IN A MOUND OF EARTH AND A CHARRED STAKE.
IN 1991 TUTTLE FOUND A 17"X12"X10" STONE.
IN 1998 EDWARDS SET A 2 3/8" BC STAMPED AS BELOW. SET \triangleright POST

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

 \triangleright \triangleright \triangleright 5/8" IRON I 5/8" IRON I 5/8" IRON I 5/8" IRON I 2 3/8" BC ROD ROD HTIW HTIW H A PLASTIC H A PLASTIC H A PLASTIC MXD MXD D "951" LIES N 42'24'11" W, 10 "951" LIES S 34'48'10" W, 10 "951" LIES S 22'02'47" W, 20 "#951" LIES S 61'52'08" F 162.77 244.55 22.91 F FEET

FEET


ROD WITH A PLASTIC CAP MKD Ţ 152.26 FEET

STAMPED AS BELOW.

MONUMENT DETAIL

SKETCH

5/8" IRON ROD WITH PLASTIC CAP, MKD "#951"



CANAL ROAD

SECTION: CORNER

15226,

5/8" IRON ROD WITH PLASTIC CAP. MKD "#951"

10000

READ AL PROPER

S 22.02'47"

_5/8" IRON ROD WITH PLASTIC CAP. MKD "#951"

MONUMENT SET

PROCEDURES AND DESCRIPTION)

"5/8" IRON ROD WITH PLASTIC CAP. MKD "#951"

NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

IN FENCE LINE ±100' EAST OF IRRIGATION CANAL.

COMPASS DEC.

PRIMM LAND SURVEYING P.O. BOX 1322 HERMISTON, OREGON 97838 FIRM/AGENCY

PARTY ָס.

KEITH P. WITNESS PRIMM

> SURVEYOR'S SEAL

LAND SURVEYOR REGISTERED PROFESSIONAL

0

OREGON
JULY 12, "
KEITH F

, 2, 2005 H P PRIMM 48490

EXPIRATION DATE: 12/31/20

草

DEC 0