CORNER RESTORATION FORM

Township 4N Range 29E, 30E Section 13,18,19,24 County OMATILIA
State OREGON Date 3/30/2023 Number N-25 X Condition Report Only
Corner Designation: SECTION CORNER:13, 18, 19, 24 Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER Surveyed In Referenced
ORIGINALLY SURVEYED IN 1860 BY CAMPBELL UNDER
CONTRACT 95, HE SET A POST IN MOUND OF EARTH MONUMENT DETAIL
1998 EDWARDS SET A 1"X30" I.P. W/2 3/8" BRASS CAP X Found Set
COUNTY SURVEY NO. 98-213-C
2013 EDWARDS SET A 2 1/2" BRASS CAP COUNTY SURVEY NO.
13-532-C R29E R30E
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: NORTHING: 788362.94 S13 S18 S24 S19
EASTING: 8553386.70
2013
Monument & Accessories Set/Found (Procedure and Description)
AT CORNER FOUND A 2 1/2" BRASS CAP 2' BELOW GRADE IN FIELD, COUNTY SURVEY NO. 13-532-C
FOUND A 5/8" IRON ROD N 82°49' E 51.92' IN EDGE OF DIRT ROAD 2" BELOW GRADE, CORNER FORM NO. N2513-532-C
FOUND A ALUMINUM TAG "951" & UMATILLA MON. SIGN ON POWER POLE N 51°13' E 32.21', CORNER FORM
NO. N25-98-213-C
FOUND A 5/8" IRON ROD W/PLASTIC CAP 951 S 05"12' E 327.97', CORNER FORM NO. N25-13-532-C
FOUND A 5/8" IRON ROD W/YELLOW PLASTIC CAP "PLS LS 48490" S 21"16' E 28.21', CORNER FORM NO.
N25-21-004-C

