CORNER RESTORATION FORM

(N) - 007 G (1) 47 40 40 90 G (4 UMATULA
Township 4N Range 29E Section 17,18,19,20 County UMATILLA
State OREGON Date 3/30/2023 Number N-5 X Condition Report Only
Corner Designation : SECTION CORNER: 17, 18, 19, 20 Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER Surveyed In Referenced
ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER
CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH MONUMENT DETAIL
1989 EDWARDS SET A 2 3/8" BRASS CAP COUNTY SURVEY NO. X Found Set
89-137-B
T4N R29E
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: NORTHING: 787754.28
EASTING: 8526975.23
Monument & Accessories Set/Found (Procedure and Description)
AT CORNER FOUND A 2 3/8" BRASS CAP 5" DEEP BELOW GRAVEL ROAD, COUNTY SURVEY NO. 89-137-B
FOUND ALUMINUM TAG 951 ON RXR TIE S 21°11' E 61.56', AS PER CORNER FORM N5-02-048 & N5-21-004
FOUND 5/8" IRON ROD-6" BELOW GRADE S 88°41' W 29.98', AS PER CORNER FORM N5-02-048 & N5-21-004
FOUND ALUMINUM TAG 951 ON P.P STUB & UMATILLA MON. SIGN S 61°50' W 23.88', AS PER CORNER FORM
N5-02-048 & N5-21-004
FOUND A 1/2" IRON ROD 8" DEEP N 88°38' E 18.51', AS PER CORNER FORM N5-02-048 & N5-21-004
FOUND A 1/2 INON ROD O DEEL IN GG GG E 10.01, INC. 121. COMMENT TOTAL
Sketch of Monument, Accessories and General Area REGISTERED
PROFESSIONAL
LANDSURVEYOR
A Marie Marie
- and
OREGON MAY 10, 2011
LANCE CLARK KING 61420
DIRT RD. DIRT RD. RENEWS: 6/30/2023
FOUND 5/8" IRON ROD 18 51 FOUND 1/2" IRON ROD CK3, LLC
29.98' RON ROD CK3, LLC 945 W. ORCHARD
HERMISTON OREGON 97838 OFFICE: 541-567-2345
PAX: 541-567-2305 WEB: CK3LLC.NET
Field Book# 0-350
FOUND ALUMINUM TAG 951 STUB POLE COUNTY SURVEYOR
& UMATILIA MON. RECORDING INFO
& UMATILIA MON. SIGN RECORDING INFO Received CT
FOUND ALUMINUM Figure 5/4/23
TAG 951 RAILROAD TIE Filed 5/4/25 Current No. 23-047-C

Survey No. 23-042-C

Drawing No.___

Index No. N-5