CORNER RESTORATION FORM

Township 4N Range 29E Section 21, 28 State OREGON Date 3/30/2023 Number R-11 Corner Designation: 1/4 CORNER: 21, 28 Previous Renewals ORIGINAL SOURCE OF CORNER ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH 1995 EDWARDS SET A 5/8" I.R. W/2" ALUMINUM CAP BY	County UMATILLA Condition Report Only Not Found X Renewed Surveyed In X Referenced MONUMENT DETAIL X Found Set
SINGLE PROPORTION COUNTY SURVEY NO. 95-060-B &	
CORNER FORM NO. R11-95-060-B	T4N R29E
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE: NORTHING: 782659.18	$\begin{pmatrix} 1 & 21 \\ 4 & -28 \end{pmatrix}$
EASTING: 8534960.79 Monument & Accessories Set/Found (Procedure and Description)	
AT CORNER FOUND A 2" ALUMINUM CAP 1/2" BELOW ASPHALT, RESTAMPED/REFRESHED MONUMENT AS SHOWN	STAMPED/REFRESHED MONUMENT AS SHOWN

FOUND COUNTY FOUND FOUND A R11-95-060-B ⊳ SURVEY NO. 1"X30" 1/2"X24" I.R. W/2"ALUM. ALUM. TAG 951 ON RXR TIE FENCE COR. N 78°54' E 203.01', CORNER FORM NO. I.R. 95-060-В, ₩/2 3/8" BRASS CAP ۵۰ CAP CORNER FORM NO. R11-95-060-B S 01°02' E 30.05', CORNER FORM NO. R11-95-060-B દ્રુ UMATILLA MON. SIGN N 00°50' E 29.91', CORNER FORM NO. R11-95-060-B

SET A 5/8" I.R. W/RPC "PLS 61420", S 64°49' W 49.05'

