CORNER RESTORATION FORM

Township 4N Range 29E Section 22, 27	County UMATILLA
State OREGON Date 3/30/2023 Number R-15	X_Condition Report Only
Corner Designation: 1/4 CORNER: 22, 27	Not Found Renewed
Previous Renewals ORIGINAL SOURCE OF CORNER	Surveyed In
ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER	INSTELLEMENT
CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH	MONUMENT DETAIL
1998 EDWARDS SET A 1"X30" I.P. W/ 2-3/8" BRASS CAP BY	
SINGLE PROPORTION COUNTY SURVEY NO. 98-213-C &	
CORNER FORM NO. R15-98-213-C	T4N R29E
BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:	4 0 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
NORTHING: 782819.04	27
EASTING: 8540227.81	1998
Monument & Accessories Set/Found (Procedure and Description)	
AT CORNER FOUND A 2 3/8" BRASS CAP & UMATULA MON. SIGN. COUNTY SURVEY NO. 98-213-C & CORNER	COUNTY SURVEY NO. 98-213-C & CORNER



