## OREGON CON RESTORATION FORM SECTION 23 TOWNSHIP 4 NORTH RANGE 29 EAST COUNTY: UMATILLA DATE 11-2001 CORNER DESIGNATION \_\_CONDITION REPORT ONLY NOT FOUND X\_RENEWED SW CORNER \_\_UNCOVERED SURVEYED IN X\_REFERENCED PREVIOUS RENEWALS / SURVEYS, ETC. ORIGINALLY SURVEYED IN 1860 BY DAVENPORT UNDER CONTRACT #101. HE SET A POST IN A MOUND OF EARTH AND A CHARRED STAKE. IN 1998 EDWARDS SET A 5/8"X30" IRON REBAR WITH 2" ALUMINUM CAP 20.00 FEET NORTH OF A 2 1/2" B.C. W.C. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE FOUND A 2" ALUMINUM CAP STAMPED AS BELOW FLUSH WITH THE PAVEMENT. AN ALUMINUM TAG #951 IN A POWER POLE BEARS S 13'24'02" W 12.36 FEET. AN ALUMINUM TAG #951 ON A BRACE POST BEARS N 55'12'32" E 48.64 FEET. AN ALUMINUM TAG #951 ON A POWER POLE BEARS N 2"20'40" E 29.43 FEET. A 2 1/2" BRASS CAP WITNESS CORNER (UNREADABLE) BEARS S 0"14"51" W 20.00 FEET. MONUMENT DETAIL T4N R29E 22 | 23 27 7 26 FEEDVILLE ROAD 1998 LS 951 IRON REBAR NAD 83/91 OREGON STATE PLANE INTERNATIONAL FEET 782887.8800 8542885.1246 MONUMENT SET ( PROCEDURES AND DESCRIPTION ) NEW ACCESSORIES FROM WHICH A 5/8"X30" IRON REBAR WITH PLASTIC CAP #48509 LIES S 67"37"52" E 42.93 EETYVED BY Umatilla County Surveyor Date\_ Rec'd By KK COMPASS DEC. LOCATION AND COMMENTS AT THE INTERSECTION OF SURVEYOR'S SEAL FEEDVILLE ROAD AND ZABRANSKY FIRM/AGENCY LANE.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

1. Comunication

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/2001

WITNESS WALT MUNDELL

EDWARDS SURVEYING P.O. BOX 763 HERMISTON, OREGON 97838

PARTY CHIEF CURTIS FAVOREL

NOTES