## OREGON CORNER RESTORATION FO

SECTION 23

TOWNSHIP 4 NORTH RANGE 29 EAST

COUNTY: UMATILLA

DATE 11-2001

CORNER DESIGNATION

\_\_CONDITION REPORT ONLY

NOT FOUND X\_RENEWED

SOUTH 1/4

\_\_UNCOVERED SURVEYED IN X\_REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101. HE SET A POST IN A MOUND OF EARTH AND A CHARRED STAKE.

ASCHER FOUND A 5/8" IRON REBAR IN 1967.


IN 1998 EDWARDS PLACED A 2" ALUMINUM CAP ON A 5/8" IRON REBAR.

## MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

FOUND A 2" ALUMINUM CAP 2" BELOW PAYED SURFACE. FROM WHICH:

AN ALUMINUM TAG #951 ON A R.R. TIE FENCE POST BEARS N 43°43'59" E 30.57 FEET.

AN ALUMINUM TAG #951 ON A POWER POLE BEARS S 25°44'29" E 50.58 FEET.
AN ALUMINUM TAG #951 ON A POWER POLE BEARS S 83°57'27" W 162.44 FEET.



MONUMENT SET

( PROCEDURES AND DESCRIPTION )

## NEW ACCESSORIES FROM WHICH

A 5/8"X30" IRON REBAR WITH PLASTIC CAP #48509 BEARS S 80"34"58" E 86.88 FEET NED BY

COMPASS DEC.

Umatilia County Surveyor

Date\_\_

SURVEYOR'S SEAL

LOCATION AND COMMENTS
AT THE INTERSECTION OF LOOP

ROAD AND FEEDVILLE ROAD.

FIRM/AGENCY EDWARDS SURVEYING

P.O. BOX 763 HERMISTON, OREGON 97838

PARTY CHIEF CURTIS FAVOREL

NOTES

WITNESS

WALT MUNDELL

REGISTERED PROFESSIONAL LAND SURVEYOR

Menn devak OREGON

JULY 16, 1971

G. DENNIS EDWARDS

RENEWS 12/31/2001