CORNER RESTORATION FORM

AT CORNER FOUND A 2 1/4" BRASS CAP & SET A UMATILLA MON. SIGN, COUNTY SURVEY	Monument & Accessories Set/Found (Procedure and Description)	EASTING: 8524519.10	NORTHING: 777141.24	BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE	V3-98-155-C	COUNTY SURVEY NO. 98-155-C & CORNER FORM NO.	1998 HADDOCK RESET A 1"X30" I.P. W/2 1/4" BRASS CAP	1973 KRUMBEIN SET BRASS CAP COUNTY SURVEY NO. I-021-C	CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH	ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER	Previous Renewals ORIGINAL SOURCE OF CORNER	Corner Designation: 1/4 CORNER: 30, 31	State_OREGONDate3/30/2023_NumberV-3	Township_4NRange29ESection_30, 31
SIGN, COUNTY SURVEY NO. 98-155-C &	00	4 1973 8 5 7 7 7 7 8	4 1998	U1 S30	SC RC	LLA CO.		X Found Set	MONUMENT DETAIL	- Notice Caroon	Surveyed In	Not Found Renewed	XCondition Report Only	County_UMATILLA

FOUND A 3/4"X27" IRON PIPE BENT NO. V3-95-060-B CORNER FORM NO. V3-98-155-C
FOUND A 1/2"X24" IRON ROD W/ALUMINUM CAP 951 SOUTHWEST TIED ₩.C., SPINHOLE 1' BELOW GRADE Z 88°48' Ħ N 01°12' 10.11', CORNER FORM NO. * 9.90', CORNER FORM

FOUND A 5/8" CORNER FORM V3-95-060-B 1 1/4"X34" IRON ROD 1" IRON ROD W/YELLOW NO. V3-02-49-G BELOW PLASTIC CAP GRADE "PLS ß 88°51' ST 48509" 8" * 9.98', CORNER BELOW GRADE FORM NO. ß 01°17' V3-95-060-B Ħ 10.00

Sketch FOUND 1 1/4"X34" IRON ROD of Monument, FOUND 1/2"X24" IRON 2" ALUMINUM CAP 951 Accessories FOUND 5/8" IRON ROD W/YELLOW PLASTIC CAP "PLS LS 48509" -'00.01-6.90 ROD W/ W.C. 10 and FOUND
3/4"X27"
IRON PIPE General Area FEEDER DITCH Survey Index Drawing No. Received CK3, LLC
945 W. ORCHARD
HERMISTON OREGON 97838
OFFICE: 541-567-2345
FAX: 541-567-2305
WEB: CK3LLC.NET
Field Book # 0-350 Field Book# Agency: MAY 10, 2011 LANCE CLARK KING 61420 COUNTY SURVEYOR RECORDING INFO RENEWS: 6/30/2023 REGISTERED PROFESSIONAL LAND SURVEYOR No. No. c -042-2