OREGON CORNER RESTORATION FORM

SECTION 31,36 TOWNSHIP 4 NORTH RANGE 28 & 29 EAST

COUNTY : UMATILLA

DATE 01/02

CORNER DESIGNATION

X CONDITION REPORT ONLY

X-1

__ NOT FOUND __ RENEWED

__UNCOVERED

__ SURVEYED IN __ REFERENCED

1/4 CORNER

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1860 BY CAMPBELL UNDER CONTRACT #95. HE SET A POST IN A MOUND. IN 1980 KRUMBEIN SET A B.C. SEE SURVEY #S-156.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

AN ALUMINUM TAG #951 ON A 5" X 5" STEEL POST LIES N 12'06'04" W, 81.74 FEET.
AN ALUMINUM TAG #951 ON A R X R TIE FENCE POST LIES S 66'06'16" W, 7.67 FEET.
A 1 3/8" × 32" I.D. IRON PIPE LIES S 89'51'34" E, 14.91 FEET.
A 1" × 36" IRON PIPE LIES N 00'17'21" W, 10.02 FEET.

MONUMENT DETAIL

SKETCH

NAD 83/91 OREGON STATE PLANE INTERNATIONAL FEET

> 774451.0985 8521362.4133

ALUM. TAG
ON 5' X 5'
STEEL POST

Z

I' X 36'
IRON PIPE

N 00'17'21' V
10.02'

S 89'51'34' E
14.91'

ALUM. TAG
R X R TIE
FENCE POST

ALUM. TAG
R X R TIE
FENCE POST

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

COMPASS DEC.

FROM INTERSECTION OF ECHO MEADOWS RD. AND UMATILLA MEADOWS RD. GO WEST 1/2 MILE THEN NORTH 1/2 MILE ACROSS FIELDS TO COR.

LOCATION AND COMMENTS

FIRM/AGENCY
PRIMM LAND SURVEYING
P.O. BOX 1322
HERMISTON, OREGON 97838

PARTY CHIEF KEITH P. PRIMM

NOTES

WITNESS BRIT L. PRIMM SURVEYOR'S SEAL

Dals.

RECEIVED BY Umaklik County Surveyo

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 13, 1999 BRIT L. PRIMM 48509

EXPIRATITION DATE:12/31/02