## OREGON CORNER RESTORATION FORM

SECTION 36

TOWNSHIP 4 NORTH RANGE 29 EAST

X-25

COUNTY: UMATILLA

DATE 8-98

CORNER DESIGNATION

\_\_CONDITION REPORT ONLY

\_\_NOT FOUND \_\_RENEWED

EAST 1/4

UNCOVERED X SURVEYED IN X REFERENCED


PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINALLY SURVEYED IN 1860 BY CAMBELL UNDER CONTRACT #95. HE SET A POST IN A MOUND OF EARTH AND A CHARRED STAKE.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE NOTHING

SKETCH

## MONUMENT DETAIL



( PROCEDURES AND DESCRIPTION )

BY SINGLE PROPORTION, I SET A 1" X 30" IRON PIPE WITH A 2 3/8" BRASS CAP STAMPED AS ABOVE. BRASS CAP LIES 3" ABOVE THE SURFACE.

## NEW ACCESSORIES FROM WHICH

AN ALUMINUM TAG, #951, ON A POWER POLE LIES S 12'.59' W, 109.25 FEET.
A 5/8" X 30" IRON REBAR WITH PLASTIC CAP #951 LIES S 78'.48'47" W, 233.41 FEET.
AN ALUMINUM TAG, #951, ON A POWER POLE, LIES N 5'.51'50" W, 218.94 FEET.
A 5/8" X 30" IRON REBAR WITH PLASTIC CAP, #951, LIES N 89'.52'24" E, 68.18 FEET.

LOCATION AND COMMENTS

FROM INTERSECTION OF STAGE GULCH ROAD AND LARGE POWER LINE, GO SOUTH ALONG POWER LINE 0.5 MILES TO CORNER.

COMPASS DEC.

SURVEYOR'S SEAL

FIRM/AGENCY EDWARDS SURVEYING P.O. BOX 763 HERMISTON, OREGON 97838 97838

RECEIVED BY

Umatilla County Surveyor

Date\_ 10 -98 Rec'd By No. 78-213 PARTY CHIEF D. EDWARDS

NOTES

WITNESS RICK SMITH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

& Donin Edward

OREGON JULY 16, 1971
G. DENNIS EDWARDS
951
RENEWS 12/31/99