## OREGON CORNER RESTORATION FORM

SECTION 34,3 TOWNSHIP 4&3 NORTH RANGE 29 EAST

COUNTY: UMATILLA

DATE 11/01

CORNER DESIGNATION

X CONDITION REPORT ONLY

Z-15

\_\_NOT FOUND RENEWED

\_\_UNCOVERED

SURVEYED IN X REFERENCED

1/4 CORNER

## PREVIOUS RENEWALS / SURVEYS, ETC.


ORIGINALLY SURVEYED IN 1859 BY GATES UNDER CONTRACT #84. HE SET A POST

IN A MOUND OF EARTH.

IN 1998 EDWARDS SET A 1" x 30" IRON PIPE WITH A 2 3/8" BRASS CAP BY SINGLE PROPORTION.

## MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

AN ALUMINUM TAG #951 ON A POWER POLE LIES N 62'56'56" W, 58.38 FEET. AN ALUMINUM TAG #951 ON A POWER POLE LIES N 7'43'14" E, 108.42 FEET. AN ALUMINUM TAG #951 ON A POWER POLE LIES N 63'17'39" E, 83.56 FEET. AN ALUMINUM TAG #951 ON A R x R TIE LIES S 14'03'56" E, 14.40 FEET.



NEW ACCESSORIES FROM WHICH

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By KK

No. D1-213-9

SURVEYOR'S SEAL

LOCATION AND COMMENTS AT THE INTERSECTION OF OLD STAGE GULCH ROAD AND

COOPER ROAD.

FIRM/AGENCY

COMPASS DEC.

PRIMM LAND SURVEYING P.O. BOX 1322 HERMISTON, OREGON 97838

PARTY CHIEF KEITH P. PRIMM

NOTES

WITNESS BRIT L. PRIMM

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JULY 13, 1999 BRIT L. PRIMM

48509 EXPIRATITION DATE:12/31/02