OREGON CORNER RESTORATION FORM

SECTION 36

TOWNSHIP 4 NORTH RANGE 29 EAST

Z - 23

COUNTY: UMATILLA

DATE 8-98

CORNER DESIGNATION

__CONDITION REPORT ONLY

_ NOT FOUND __ RENEWED

SOUTH 1/4

__ UNCOVERED X SURVEYED IN X REFERENCED


PREVIOUS RENEWALS / SURVEYS. ETC.

ORIGINALLY SURVEYED IN 1859 BY GATES UNDER CONTRACT #84. HE SET A POST IN A MOUND OF DIRT,

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

MONUMENT DETAIL

SKETCH



MONUMENT SET (PROCEDURES AND DESCRIPTION)

BY SINGLE PROPORTION I SET A 1" X 30" IRON PIPE WITH A 2 3/8" BRASS CAP STAMPED AS ABOVE, 3" BELOW THE SURFACE. OF A GRAVELED ROAD

NEW ACCESSORIES FROM WHICH

AN ALUMINUM TAG #951 ON A POWER POLE LIES N 86.06'00" W, 285.22 FEET.
AN ALUMINUM TAG #951 ON A POWER POLE LIES N 85'.21'30" E, 262.39 FEET.
A 5/8" X 30" IRON REBAR WITH PLASTIC CAP #951 LIES N 0'.03'00" W, 16.46 FEET.
A 5/8" X 30" IRON REBAR AND PLASTIC CAP #951 LIES S 0'.03'00" E, 17.83 FEET.

LOCATION AND COMMENTS

COMPASS DEC.

SURVEYOR'S SEAL

REGISTERED

PROFESSIONAL LAND SURVEYOR

FIRM/AGENCY EDWARDS SURVEYING P.O. BOX 763 HERMISTON, OREGON 97838

97838

RECEIVED BY

PARTY CHIEF D. EDWARDS

Umatilla County Surveyor

NOTES

WITNESS

CURTIS J FAVOREL

D. Comis Show OREGON JULY 16, 1971 G. DENNIS EDWARDS 951

RENEWS 12/31/99

Rec'd By