

# OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 04/10/17

CORNER DESIGNATION: N-13, The Northeast Corner of Section 21, Township 4 North, Range 34 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by William Odell under Contract No. 114, dated July 2, 1866. Notes state: set post corner for sections 15, 16, 21, and 22, drove charred stake, dug pits, and raised mound as per instructions.

MONUMENT AND ACCESSORIES FOUND: Held the intersection of a farmed field berm extending North and East as the best remaining evidence of the original corner.

## MONUMENT MARKING DETAIL:

T4N R34E  
S16|S15  
S21|S22  
2017  
PLS 54657

MONUMENT SET: At the corner point set a 2 3/8" dia. brass cap on a 1 1/4"x30" galvanized iron pipe with the top 14" below ground level in an unfarmed area where farmed fields come together. Monument marked as shown in "Monument Marking Detail".

## From which:

A 5/8"x24" rebar with 1 1/4" blue plastic cap stamped "Wells Surveying PLS54657" 22" below ground level in farmed field bears Grid Azimuth 41°18'12", 32.4 feet (ground distance).

A 5/8"x24" rebar with 1 1/4" blue plastic cap stamped "Wells Surveying PLS54657" 22" below ground level in farmed field bears Grid Azimuth 127°17'16", 38.0 feet (ground distance).

A 5/8"x24" rebar with 1 1/4" blue plastic cap stamped "Wells Surveying PLS54657" 22" below ground level in farmed field bears Grid Azimuth 218°21'35", 43.5 feet (ground distance).

A 5/8"x24" rebar with 1 1/4" blue plastic cap stamped "Wells Surveying PLS54657" 22" below ground level in farmed field bears Grid Azimuth 297°54'45", 40.3 feet (ground distance).

Buried bearing object signs with rebar.

LOCATION AND COMMENTS: Corner is located in an unfarmed area where farmed fields come together.

FIRM: Wells Surveying  
P.O. Box 1696  
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

/4N34N13



RENEWS: 6:30:18

17-048-0