

Oregon Corner Re-station Form

Section 25-36 Township 4N Range 34E W.M.

County Umatilla Date October 20, 1997

Corner Designation V-23

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

25
36
 T4N R34E


Previous Renewals / Surveys, etc.

W. Odell set a corner post, with charred stake, mound, and pits in 1866. In remeasuring the Umatilla Reservation Boundary in 1887, Currin and Noland found the post, mound, and pits.


Monument(s) & Accessories Found: (Condition and Source)

Found an 8" x 8" Railroad Tie post said to be the remains of a four way fence corner, and the Quarter corner.

Monument Detail



Sketch



Monument Set (Procedures and Description)

I set a 2 1/2" Brass Cap for the corner along the East side of the post.

New Accessories

- A 5/8" rebar w/ "Bearing Object" sign attached bears N45°E, 6.72 feet.
- A 5/8" rebar w/ "Bearing Object" sign attached bears S64°E, 5.21 feet.
- A 5/8" rebar w/ "Bearing Object" sign attached bears N29°W, 7.81 feet.
- A 5/8" rebar w/ "Bearing Object" sign attached bears S34°W, 6.46 feet.

Location & Comments

Corner is located one half mile West of Pambrun Road.

Compass Declination 21.5° E

Firm:


Dwight M. Bartleson L.S.
79902 LaMar Gulch Road
Athena, OR 97813

Party Chief: D. Bartleson


Notes D. Bartleson

Witness none

Surveyor's Seal



Dwight M. Bartleson



Renews: Dec. 31, 1997

97-199-B