OREGON CORNER DESTORATION FORM

COUNTY: Umatilla

DATE: July 27, 2006


CORNER DESIGNATION: T-17 East 1/4 Corner Section 27, T. 4 North, Range 36 E.W.M.

PREVIOUS RENEWALS/SURVEYS ETC.

William Odell set a post and scribed two bearing trees (Contract No. 114, dated July 2, 1866).

MONUMENT AND ACCESSORIES FOUND: None





SKETCH:

NO SCALE

NOTE: BEARINGS AND DISTANCES
ARE NAD 'B3 ('91) GRID

N88 '39 '53 'E

38.59 'TO

THIS PIN

S88 '39 '53 'W

21.49 'TO

THIS PIN

S88 '39 '53 'W

11.58 'TO

THIS PIN

N88 '39 '53 'W

11.58 'TO

THIS PIN

N88 '39 '53 'W

THIS PIN

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD'83('91), INT. FEET:

NORTH: 783, 452.96

EAST: 8, 764, 463.90

SET 2" ALUMINUM CAP ON 5/8" X 30" G.I.P. 4" BELOW GROUND

SET 5/8" X 24" STEEL REBAR WITH BLUE PLASTIC CAP MARKED "UCPWD...LS2627"

MONUMENT SET (PROCEDURES AND DESCRIPTION):
Held the line between the monument set at
the Northeast Corner of Section 27 and the
monument set by Bill Wells at the Southeast
Corner of Section 27 for longitude and an
east-west fence to the west for latitude
and set a 5/8" X 30" steel rebar with 2"
aluminum cap marked as shown above 4" below
the surface of the county road shoulder.
NEW ACCESSORIES:

A 5/8" X 24" steel rebar with blue plastic cap marked "UCPWD...LS2627" set on the county road R/W line bears S8857*39'53"W, 21.49'. A bearing object tag is wired to the rebar.

A 5/8" X 24" steel rebar with blue plastic Northeast approach A 5/8" X 24" steel rebar with blue plastic Northeast of rebar.

A 5/8" X 24" steel rebar with blue plastic cap marked "UCPWD...LS2627" set on the county road R/W line bears N8857 $^{\circ}39'53"E$, 38.59'. A bearing object tag is wired to the rebar.

A 5/8" X 24" steel rebar with blue plastic cap marked "UCPWD...LS2627" set on the county road R/W line bears N8857*39'53"E, 28.68'. A bearing object tag is wired to the rebar.

LOCATION AND COMMENTS:
The monument is set 4" below the surface of the county road shoulder where the road crosses an east-west fence line to the west approximately 0.2 mile north of State Highway 204.

COMPASS DECLINATION:
N/A

FIRM/AGENCY: Umatilla County Road Dept. 3920 Westgate Pendleton, Oregon 97801 PARTY CHIEF:

Gary Roberts NOTES: None

WITNESS:

None

SURVEYOR'S SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON OULY 30, 1993 GARY R. ROBERTS

RENEWS 12/31/06

06-473-C