4N, R 36E. , W.M.

History of original corner establishment:

originally established by Milliam Odell, U.S. Deputy Surveyor, to. 114, Odted July 2, 1866. The original notes state that wood post was set from which:

onumented by PLS 1106 in 1979. See map filed in County

Corner Code No. V-17 Note: Monument marked as shown below

DIAGRAM

TAN R36E S27 | S26 934 935 1979

PLS 1106

Compass Declination: 19.0°

## Description of corner evidence found:

A 3" brass cap on a 2 1/2" galv. iron pipe protruding 6" from the ground, at a fence corner with old fences going east and south from which:

A sawn 36" ponderosa pine stump bears S45°W 31.0' with scribes "BT" visible on lower blaze. A rotted pine stump bears S25°E 64.0' with scribes rotted off.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained existing monument by building a stone mound around it. Marked new bearing trees as follows:

A 18" ponderosa pine bears N88°E 55.6' scribed T4N R36E S26 BT. A 17" ponderosa pine bears S65°E 141.1' scribed T4N R36E S35 BT. A 16" ponderosa pine bears N2°W 85.1' scribed T4N R36E S27BT. No tree available in the SW quadrant.

Attached bearing object signs to the new bearing trees and the original SW bearing tree stump. Placed a steel fence post North of corner and attached witness corner sign.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 22, 19/7 WILLIAM R. WELLS 1106

Willi R. Wells

7-27-88

670-700-276

Orac County of Mmatella ....... . I hereby certify that the within instrument was filed in this office for record on the 23 day of July by hallen & Amsheuer (COUNTY OFFICIAL) DEPUTY

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor