T 4N, R 36E., W.M.

History of original corner establishment:

This corner was originally established by Milliam Odell, U.S. Deputy Surveyor, under Contract No. 114 gated July 2, 1866. The original notes state that at the corner a wood post was set for the corner along with a charred stake and stone mound.

In 1897, during his County Survey No. 95, John Kiebrell recovered the corner as follows:

I find the old 1/4 sec, corner which is old stone gound about 75 lks west of caving as indicated and described by old settlers. From this corner i run 514°30'E between Secs. 32 and 33.

Corner Code No. X-9
Note: Monument marked as shown below

DIAGRAM TAN R36E

> 1/4 \$32 | \$33 1988

PLS 1106

Corper No. Compass Declination: 19.0°

Description of corner evidence found:

Found mound of stone about 75 lks west of a rayine. There are remains of an old post and rail fence running west from the stone mound.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position of the stone mound, set a 2 1/2" brass cap on a 1 1/2" by 30" galv. iron pipe 24" in the ground and surrounded with a mound of earth and stone. Referenced the corner with reference monuments as follows:

A 1 1/2" plastic cap marked "W.R. Wells, PLS 1106", set on a 5/8" by 30" iron pin bears N68°W 15.0'. Set steel fence post by the reference monument and attached bearing object sign.
A 1 1/2" aluminum cap, marked as shown below, set on a 5/8" by 30" iron pin, bears N30°E 15.3'. Set steel fence post by reference monument and attached bearing object sign.

Set steel fence post east of corner and attached witness corner sign.

The aluminum cap on the reference monument is marked:

1/4 S33 15.3 Ft 1106

> REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

7-27-88

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyere 700-170
Date 2-87

No. 88-42-C