CE. IFIED RECORD OF LAND CORNER MONUMENTATION

4N, R 36E. , W.M.

History of original corner establishment:

This corner was also surveyed to and made an angle point in in the centerline of County Road No. 330, when this County Road was surveyed by John Kimbrell.

Corner Code No. Z-13 Note: Monument marked as shown below

DIAGRAM TAN RIGHE 533 | 534 94 83 T3N R36E 1988 PLS 1106

Compass Declinations 19.0°

Description of corner evidence found:

Angle point in County Road No. 330 with roads running East-West and Southwest.

Description of monument and accessories I established to perpetuate the original location of this corner:

Reestablished corner position at the intersection of centerlines of County Road No. 330, now running East-West and Southwest from the corner point. This position was confirmed by survey measurements to corners to the East and West of the reestablished corner position. Since the reestablished corner position falls in the graded portion of the county road, the top of the monument was buried 8" below the ground surface. Set a 2 1/2" brass cap on a 1 1/2" by 30" galv. iron pipe, 38" in the ground from which:

A 7" ponderosa pine bears $$1^\circ\text{W}$$ 68.2' scribed T3N R36E S4 BT. A 10" douglas fir bears $$569^\circ\text{E}$$ 87.3' scribed T3N R36E S3 BT. An aluminum nail in the North side of power pole No. 340001 bears N66°E 18.8'. The aluminum nail is about 6" above ground.

Attached bearing object signs to each bearing tree and set a steel fence post 11.5' North of corner and attached witness corner and bearing object signs.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

7-27-88 County of Magtella JAHLEEM LAMODELLACE DAVID HE KAUPERENTON COUNTY OFFICIALI Umatilla County Surveyor

Form R6-7100-57 (9/71)