T 4N. R 36E. . W.M.

History of original corner establishment:

Corner Code No. Z-17 Note: Monusent sarked as shown below

DIAGRAM

T4N R36E 834 | 835 83 | 82

T3N R36E 1988

PLS 1106

Corper No. Compass Declination: 19.0°

Description of corner evidence found:

Fence lines running North-South and West.

This corner was originally established by Odell and Lewis, U. S. Deputy Surveyors, under Contract No. 110, dated February 7, 1865, The original notes state that at the corner a wood post was set from which:

Description of monument and accessories I established to perpetuate the

original location of this corner:

Accepted fence corner with fences running North-South and West as the best remaining evidence of the original corner position after measuring to corners to the East, West, and North. At the reestablished corner position, set a 2 1/2" brass cap on a 1 1/2" by 30" galv. iron pipe 24" in the ground and surrounded with a mound of earth and stone. From the reestablished corner position:

A 16" douglas fir bears S15°E 162.5' scribed T3N R36E S2 BT. A 10" western larch bears S20°W 35.4' scribed T3N R36E S3 BT. A 11" douglas fir bears N57°W 45.3' scribed T4N R36E S34 BT. No tree available in Northeast quadrant.

Attached bearing object signs to each bearing tree and set a steel fence post South of corner and attached witness corner sign.

REGISTERED PROFESSIONAL LAND SURVEYOR

Welli- R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

7-27-88

Office of SUNDEY County of Amatila

State of Office for record on the 28, day of July by Salder Sund Amabian (COUNTY OFFICIAL)

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Chiadra County Surveyor

Rec'd By XA