USDA-FOREST SERVICE	
Index File No. <u>E-4</u>	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No
T 4 N R. 38 E	R.D. Walla Walla County Umatilla
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T4N S38E	·
1	None. Corner established with this survey.
S 6	
E 1/16 ——————————————————————————————————	
N S /	
1988	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	None.
PHOTO IDENTIFICATION DATA	
Photo NoFiled At	
Object-Ident.	DESCRIPE CORNER LOCATION OF ATIVE TO NEAD BY
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7	Company in least 1 and 1
PLANE COORDINATE POSITION DATA	Corner is located on a ridgetop about 300' East of a draw.
State Zone	There is a fence bearing N19 <sup>O</sup> W, 75' East of corner and
x	a fence bearing E-W about 275' South of corner.
Υ	•
Estab. By	
Signature 8	Title Division Headquarters Date 50 7400 50 (200)
Willi R. Well	Title Division Headquarters Date FS-7100-52 (3/68) Land Surveyor Pendleton, Or. 9-02-88

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At position determined by survey... Set  $2\frac{1}{2}$ " aluminum cap on  $2\frac{1}{2}$ " x 30" aluminum pipe 22" in ground to bedrock & surrounded with mound of earth & stone. Set 6' fence post South of corner with signs 54-9 & 54-2 attached. Cap marked as shown in corner diagram. Compass declination 19° East. ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE There are no trees within limits, so I marked 2 bearing objects as

follows: A 18"x12"x12" above ground point on a large rock outcrop brs S31 W, 115.1' marked "XBO" on East face. Bearing object is near the Southeast edge of the rock outcrop, which is about 50' E-W dimension & 200' N.S. dimension. A 6'x6' flat spot on the same rock outcrop, at the East edge of the

outcrop, brs  $S52\frac{1}{2}^{O}W$ , 110.1' marked "XBO" on top. This area was marked

Work Done By. W.R. Wells

Index File No. E-4

REMARKS because it offers one of the only smooth, flat spots on the outcrop.

Certified Cor. Record Prepared ? Yes XNXX Filed At: County Surveyor

T. 4 N

Painted the "XBO" marks in red paint.

**R.** 38 E WM. Tract or Surv. No.

Title Land Surveyor Date 9-02-88 State Registration No. ORLS 1106

Date

Cor.