


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

F-4

History of original corner establishment:

None. Corner established with this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Since the corner falls in the South edge of a trail up the South Fork Walla Walla River...

A 2 1/2" aluminum cap on 2 1/2"x30" aluminum pipe was set with the top of the cap buried 6" below the trail level. Did not set a steel fence post on property lines since wood posts are installed at this trail crossing, attached sign 54-9 to wood post North of corner.

New bearing trees established:

A 17" ponderosa pine brs N21 1/2° E, 59.2' scribed NE1/16S7 BT.
A 19" douglas fir brs N56 1/2° W, 71.7' scribed NE1/16S7 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9 to each BT and painted face of blaze & 6" red band around each BT.

Compass declination 13° East.

I hereby certify that the above described corner monument was properly established by me on September 2, 1988.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of... County Surveyor..... County of... Umatilla
State of... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the... 17th day of... October... 1988
David H. Lumberman by Katherine K. Lumberman
(COUNTY OFFICIAL) (DEPUTY)

RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor
Date: 10-88
Rec'd By: [Signature]
No. 88-64-B