USDA-FOREST SERVICE	
Index File No. <u>F-4</u>	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No
т <u>4 N</u> R. <u>38 E</u>	R.D. Walla Walla County Umatilla
Merid. <u>Willamette</u>	N.F. <u>Umatilla</u> State <u>Oregon</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T4N R38E	•
NE 1/16	None. Corner established with this survey.
s 7	
1988	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	None.
PHOTO IDENTIFICATION DATA	
Photo No.	
Filed At.	
Object-Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By Signature	
PLANE COORDINATE POSITION DATA	Corner is located 1' North of South edge of South Fork of the
State Zone	trail(s) up the South Fork of the Walla Walla River.
X	
Υ	
Estab. By	
	Title Division Headquarters Date ES_7100_52 (3/68)
Willi R. weeks	Land Surveyor Pendleton, Or. 9-02-88

•

. .

CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Since the corner falls in the South edge of a trail up the South Fork Walla Walla River... A $2\frac{1}{2}$ " aluminum cap on $2\frac{1}{2}$ "x30" aluminum pipe was set with the top of the cap buried 6" below the trail level. Did not set a steel fence post on property lines since wood posts are installed at this trail crossing, attached sign 54-9 to wood post North of corner. ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE New bearing trees established: A 17" ponderosa pine brs $N21\frac{1}{2}$ E, 59.2' scribed NE1/16S7 BT. A 19" douglas fir brs $N56\frac{1}{2}$ W, 71.7' scribed NEI/16S7 BT. New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9 to each BT and painted face of blaze & 6" red band around each BT. Compass declination 130 East. Work Done By. W.R. Wells Time Land Surveyor Dote 9-02-88 State Registration No. ORLS 1106 Certified Cor. Record Prepared ? Yes XNXX Filed At: County Surveyor Date REMARKS

Cor.